

FIELD PHOTOGRAPHY LOG SHEET

SITE NAME: Illinois Central Railroad Tracks

PAGE 1 OF 3

U.S. EPA ID: ILD980677645

TDD: F059104018

PAN: FIL0454PA



DATE: June 19, 1991 TIME: 1400

DIRECTION OF PHOTOGRAPH: NE

PHOTOGRAPHED BY: BC

WEATHER CONDITIONS: Sunny, 80°F.

SAMPLE ID (if applicable): NA

DESCRIPTION: Looking Northeast across the gravel lot, from a location outside the fence at the southwest perimeter. The location of suspected drums is in the distance, on the left.

US EPA RECORDS CENTER REGION 5



447455

FIELD PHOTOGRAPHY LOG SHEET

SITE NAME: Illinois Central Railroad Tracks

PAGE 2 OF 3

U.S. EPA ID: ILD980677645

TDD: F059104018

PAN: FIL0454PA

DATE: June 19, 1991

TIME: 1350

DIRECTION OF
PHOTOGRAPH:

E/NE

WEATHER
CONDITIONS:
Sunny, 80°F.PHOTOGRAPHED BY:
BCSAMPLE ID
(if applicable):
NA

DESCRIPTION:

Looking through the fence at storage building near gate.

DATE: June 19, 1991

TIME: 1350

DIRECTION OF
PHOTOGRAPH:
EastWEATHER
CONDITIONS:
Sunny, 80°F.PHOTOGRAPHED BY:
BCSAMPLE ID
(if applicable):
NA

DESCRIPTION:

Looking East at Storage building from gate area.



FIELD PHOTOGRAPHY LOG SHEET

SITE NAME: Illinois Central Railroad Tracks

PAGE 3 OF 3

U.S. EPA ID: ILD980677645

TDD: FO59104018

PAN: FIL0454PA



DATE: June 19, 1991

TIME: 1320

DIRECTION OF PHOTOGRAPH: SE

PHOTOGRAPHED BY: B.C.

WEATHER CONDITIONS: Sunny, 80°F.

SAMPLE ID (if applicable): NA

DESCRIPTION: Looking Southeast from entry gate area toward area of suspected barrel storage

FIELD PHOTOGRAPHY LOG SHEET

SITE NAME: Illinois Central Railroad Tracks

PAGE OF

U.S. EPA ID: ILD980677645

TDD: FO59104018

PAN: FILO454PA

DATE: June 19, 1991

TIME:

DIRECTION OF PHOTOGRAPH:

WEATHER CONDITIONS:
Sunny, 80°F.

PHOTOGRAPHED BY:

SAMPLE ID
(if applicable):

DESCRIPTION:



DATE: June 19, 1991

TIME:

DIRECTION OF PHOTOGRAPH:

WEATHER CONDITIONS:
Sunny, 80°F.

PHOTOGRAPHED BY:

SAMPLE ID
(if applicable):

DESCRIPTION:



FIELD PHOTOGRAPHY LOG SHEET

SITE NAME: Illinois Central Railroad Tracks

PAGE OF

U.S. EPA ID: ILD980677645

TDD: F059104018

PAN: FIL0454PA

DATE: June 19, 1991

TIME:

DIRECTION OF
PHOTOGRAPH:WEATHER
CONDITIONS:
Sunny, 80°F.

PHOTOGRAPHED BY:

SAMPLE ID
(if applicable):

DESCRIPTION:



DATE: June 19, 1991

TIME:

DIRECTION OF
PHOTOGRAPH:WEATHER
CONDITIONS:
Sunny, 80°F.

PHOTOGRAPHED BY:

SAMPLE ID
(if applicable):

DESCRIPTION:



FIELD PHOTOGRAPHY LOG SHEET

SITE NAME: Illinois Central Railroad Tracks

PAGE OF

U.S. EPA ID: ILD980677645

TDD: F059104018

PAN: FIL0454PA

DATE: June 19, 1991

TIME:

DIRECTION OF
PHOTOGRAPH:WEATHER
CONDITIONS:
Sunny, 80°F.

PHOTOGRAPHED BY:

SAMPLE ID
(if applicable):

DESCRIPTION:



DATE: June 19, 1991

TIME:

DIRECTION OF
PHOTOGRAPH:WEATHER
CONDITIONS:
Sunny, 80°F.

PHOTOGRAPHED BY:

SAMPLE ID
(if applicable):

DESCRIPTION:









